

# Inspector's Gamma Radiation Scanner

**Model: Rad-D-W**

## Process

Use of a radiation detector is required to do a detailed search of contents of building, container, vehicle, etc.

With the **RAD-D-W** access is not required, only proximity.

If the inspector does not have the **RAD-D-W** he/she must:

1. Must file and get authorization to enter and search the area, container, building, or vehicle.
2. Find the owner to gain access or break the locks.
3. Get one or more co-workers to help as a witness, or for security, and for technical expertise.

**Optional:** The highly sensitive Neutron Detector gives warning and confirmation that fissionable materials are present.



## Optional Mounting with Alarm Beacon:



**TECHNICAL ASSOCIATES  
OVERHOFF TECHNOLOGY**

7051 ETON AVENUE, CANOGA PARK, CA 91303  
PHONE: 818-883-7043 | FAX: 818-883-6103

SALES@USNUCLEARCORP.COM | TECH-ASSOCIATES.COM | USNUCLEARCORP.COM

DIVISIONS OF



USNUCLEARCORP

OTCQB-UCLC